COUNTYWIDE PROPERTY INSPECTIONS

9320 Willowgrove Avenue, Suite D • Santee, California 92071 • (619) 448-2874 • (888) 862-6464 • Fax (619) 448-2994

Date:		Time):	to:	Client:		D 0-11		full (= 2 th / 2 th d 2 th 2
Property	/ Addre	ss:				☐ Buyer	☐ Seller		full / part / end / absent
Inspecto	or:				Buver's	s Agent	/Asst:		
									full / part / end / absent
Seller:_				full / part / end / absent	Sellers	Agent	/Asst:		full / part / end / absent
		ON-S	ITE	/ CHECKL	I T ZI	NSPI	ECTION R	FPNRT	
		_			•			^	
DESCRIPTI	<u>ION</u> :	Single	Story	Two Story	☐ Thre		Split-Level		
YEAR BUIL	<u></u>				☐ Sq. I	Footage (ι	inverified; provided	by buyer/agent)	:
FOUNDATION: Slab on 0		Grade		☐ Raised Foundation ☐ Post / Pier					
☐ Un-reinfo		forced n	nasonry						
STRUCTUR	<u>RE</u> :	☐ Wood F	rame	Block / Brick	Cond	crete Tilt-u	ıp 🔷		
SIDING:		☐ Stucco	(Stucco	-to-grade / Weep scr	eed)		☐ Brick	☐ Stone	
		☐ Wood (T-111 / S	Shiplap / Hardboard /	Shingles/	Composit	e) Clapboard		
		☐ Vinyl		Aluminum	☐ Bloc	k			
ROOF:		☐ Comp S	Shingle		☐ Woo	od Shingle	☐ Gravel	Rolled	Synthetic
		☐ Concre	te Tile	e Tile Clay Tile		al	Fibrous		
BUILDING	WAS:	☐ Occupi	ed / Furr	nished Pa		ially Furnis	shed	☐ Vacant/Un	furnished
WEATHER:		☐ Wet		☐ Dry	☐ Clea	ar	Cloudy	Rain Ter	mp. (Approx)
located. All	orientatior	ns (FRONT, F	REAR, E	oted, the words FROI TC.) are based on FI e perspective of the e	RONT bein	ng the per			•
	PA	GE REFE	RENC	E			RECO	MMENDATIO	ONS
<u>Page 1</u> :	Report I	nformation	Summ	ary Field Report	Items in the report marked by the inspector these statements:		or will refer to		
<u>Page 2</u> :	General	Exterior					marked box - ite		is deficient (e.g.,
<u>Page 3</u> :	Gen. Ex	terior cont.	Buildir	Building Exterior		✓	damaged, improper). Recommend specialty coinspect the flagged item and its related		
Page 4:	Bldg. Ex	terior cont.	Found	ation			component to det		
<u>Page 5</u> :	Raised	aised Foundation Roof				(A)	circled 1 - recom	nmend evaluation	on and repairs as
Page 6:	Roof (co	ont.)	Attic			#1)	necessary by a qualified termite inspec		
<u>Page 7</u> :	Attic (co	nt.)	:.) Garage						
<u>Page 8</u> :	Garage	(cont.)	Laundry			#2	circled 2 - recom		
<u>Page 9</u> :	Plumbin	g	Electrial						
<u>Page 10</u> :	Electrica	al (cont.)	Heatin	g Air Conditionin	ng		informational item - condition as noted at the ti		noted at the time
<u>Page 11</u> :	Fireplac	e(s)	Interio	r Rooms			of inspection	of inspection	
Page 12:	Interior	Rooms (cont.	.)			()			ears to function as
<u>Page 13</u> :	Halls		Bedro				it was designed to	o do	
Page 14:		ns (cont.)	Bathro	ooms		\Diamond	N/A - not applicab	ole to this inspec	tion
<u>Page 15</u> :		ms (cont.)							
Recommend Client is urge	dations: R ed to cons	ecommendati sult with a qua	ons for fu alified an	orther evaluation of pro d licensed tradespers	blems and on, contra	deficiencie ctor or eng	es found in the home gineer (i.e., a special	will be noted in this list experienced v	s report. Accordingly, vith the noted problem

or deficiency) prior to close of escrow. Failure to promptly follow any recommendation(s) made in this report may result in an inadequate or incomplete inspection of the property, for which Client assumes full responsibility.

Use of Report: All information contained in this report is the exclusive property of the Client listed at the top of this page. Use of this report by a third party for purposes of purchase or evaluation of this property is not authorized.

<u>Contract Terms Apply</u>: Client acknowledges that in accepting this report, Client is agreeing to all terms and conditions contained in COUNTYWIDE'S Inspection Agreement. This Inspection Report incorporates by reference, all provisions set forth in the Inspection Agreement, including those provisions of the Agreement which disclose to the Client, components or conditions of the property that <u>will not</u> be addressed or inspected by COUNTYWIDE (i.e., which are beyond the scope of the inspection).

RECOMMENDATIONS (Rec.): = Recommend a specialty contractor further inspect to determine all repair options and costs. #1 = Recommend qualified termite inspector #2 = Recommend qualified engineer							
	GENERAL EXTERIOR	<u> </u>					
1 Driveway		avel Unimproved Tile Stone					
Satisfactory	☐ cracks – hairline	evidence of poor drainage (water stains etc.)					
☐ Rec. #1 #2	☐ cracks — 1/16" - 1/8" - 1/4" - 1/2" or greater	slopes toward structure - poss. water intrusion					
	unusually large number of cracks driveway raised and/or settled	surface damage					
	trip hazards exist	driveway higher than garage floor surface					
	☐ tree roots possibly causing damage	inappropriate drainage:					
2 Walke / Stone / Bayebas							
2 Walks / Steps / Porches	☐ Concrete ☐ Asphalt ☐ Pavers / Brick ☐ Gravel ☐ cracks — hairline	Stone Wood Tiled Metal wood damage / deterioration					
○ Satisfactory	☐ cracks — 1/16" - 1/8" - 1/4" - 1/2" or greater	handrails loose / missing / damaged					
Rec. #1 #2	walkway raised and / or settled	handrail openings greater than 4" wide					
	trip hazards at	handrailing not grippable					
	tree roots possibly causing damage	handrails too low / high					
	slopes toward foundation - poss. water intrusion evidence of poor drainage	guardrails damaged / missing / too low / too high / openings > 4"					
	separation from structure	porch - porch cover damaged / unsound					
	covers stucco weep screed or within 2"	porch separated from structure					
	wood walkway damaged	wood porch structural damage					
	step height / step depth is improper	porch - ventilation inadequate					
	steps are damaged / loose steps have wood decay	☐ Mobile home landing too low ☐ outside surface higher than / same as					
	Steps have wood decay	interior floor at					
3 Fences / Gates	☐ Wood ☐ Block ☐ Iron ☐ Chain Link ☐ S	tucco Coated					
○ Satisfactory	plants obscure fencing - a limited inspection	less than 5' high fence around pool / spa					
☐ Rec. #1 #2	uisible lean	fence / gate for pool or spa not installed					
	rotted fence posts	gate was not self closing / self latching for pool / spa					
♦ N/A	missing / loose boards fence damage	gate latch: < 3" from top (for pool)					
	fence used to retain soil	gate latch: < 54" from ground (for pool)					
	gate latch is damaged / loose	☐ glass fence not safety glass					
	gate missing / damaged / rubs						
	hardware missing / damaged						
4 Retaining Wall	^	re Cast Block Stucco Coated					
○ Satisfactory	cracks – hairline	no weep holes installed / observed					
☐ Rec. #1 #2	planter wall cracked / damaged / collapsed cracks – 1/16" - 1/8" - 1/4" - 1/2" or greater	□ block cells not filled / missing cap □ non-standard construction					
^	damage	vegetation limits access to wall-this is a					
♦ N/A	uvisible lean	limited inspection					
	wall exceeds 6' - not evaluated	retaining wall failing - engineer rec'd					
5 Visual Grade	Lot Type: Flat Minor Slope Moderate Slope (☐ Steep Slope ☐ Stair Stepped ☐ Banks					
	soil slopes toward foundation at	arth-to-wood contact					
○ Satisfactory	signs of poor drainage at	☐ planters adjacent to structure trap and					
☐ Rec. #1 #2	evidence of ponding at house perimeter	pond water					
♦ N/A	☐ faulty grade - exterior grade too high	questionable drainage atwet soils at					
Note: Scope of inspection in this section	foundation close to slope-questionable support for foundation	soil / slope retention inadequate / missing					
is limited to areas that are within 5 feet of the foundation.	□ soil erosion near foundation at	Soli / Slope retention madequate / missing					
6 Exterior Drains	None found						
	or inspected. Functional flow of any drainage system is not tested or evalu						
○ Satisfactory	drain higher than grade level strainer cap is missing / damaged / clogged	area drain cover(s) missing / damagedconcrete swale blocked by debris					
	damaged surface drain pipe	concrete swale is damaged					
		drain outlet not located					

#		ne all repair options and costs. nd qualified engineer N/A = Not applicable upears to function as it was designed to do
	General Exterior (Continued)	
7 Trees / Vegetation	☐ climbing plants growing on siding / roof	☐ roots growing underneath house
○ Satisfactory	trees / shrubs too close or touching house / roof	roots growing against house
4		
	BUILDING EXTERIOR	
8 Siding / Walls	☐ Stucco ☐ Wood ☐ Brick	☐ Vinyl ☐ Aluminum ☐ Stone
Note: If exterior siding is stucco, hairling	e cracks are not unusual unless excessive cracking is noted.	
○ Satisfactory	stucco cracks - hairline cracks - 1/16" - 1/8" - 1/4" - 1/2" or greater	wood siding is weathered / damaged
☐ Rec. #1 #2	☐ cracks – 1/16" - 1/8" - 1/4" - 1/2" or greater ☐ flaking / damage / holes in stucco	☐ flash walls have cracks / separation ☐ rusted weep screed
	exposed wire mesh / corner bead	areas of stucco patching observed
	sprinklers appear to spray on wall	moisture damage at base of wall
	excessive hairline cracking at	stucco weep screed not installed
		damaged / missing window glazing at
9 Gutters / Facia - Eaves	Full Partial None	Recommended at drip edges
○ Satisfactory	damage / deterioration	blocked drains / debris in gutter
☐ Rec. #1	improper slope / separated	downspouts terminate too close to foundation
TROOF II	☐ loose / missing gutters or pieces	missing downspouts
	☐ leaks at connection joints	a facia damage at
		☐ eave damage at
_		water stains at eaves
✓		
10 Chimney	☐ Brick / Block ☐ Stucco siding ☐ Metal flue	
Note as to precast chimneys	(if applicable): recommend independent evaluation by chimney	specialist to rule out cracking that may be obscured by
soot, (or similar) as cracking in	such chimneys usually requires a costly chimney replacement.	D
Satisfactory	spark arrestor is installed	separation from house
Rec. #2	spark arrestor not installed	cracks / deterioration at chimney crown
interior components: see page 11	spark arrestor damaged / rusted / improper	flat screen restricts flow of heat / smoke
	missing / deteriorated groutcracks / separation at bricks	chimney extends too low above roof
	flashing loose / missing / needs caulking	less than 1/4" between cap flashing and wall
	lasting loose / missing / fleeds cauking	
11 BBQ - Fireplace / Pit	Built-in Free Standing Masonry	
○ Satisfactory	no gas to BBQ / fireplace / pit	leak at drain / water supply
	☐ faulty ignitor / burners did not ignite☐ improper gas line plumbing	□ BBQ water fixture deficient□ Outlet – no GFCI / no cover
	damaged or missing BBQ parts	BBQ wiring is improper
	improper draining of sink	
	improper draining or sink	
12 Electrical		
	O avenaged remay within a	☐ GFCI failed to respond properly
○ Satisfactory	exposed romex wiringimproper conduit / connectors	missing covers for junction box(s)
	junction boxes not weatherproof	possible burnt bulb(s)
	improper wiring / unsafe	missing knock seals for junction box(s)
	missing or damaged outlet / switch cover(s)	outlet not functioning
	ungrounded outlets / reversed polarity	lightswitch has no apparent function
	no GFCI protection at the outlets	light fixture loose / damaged at
<u> </u>		
13 Waste / Drain Lines	☐ Cast Iron ☐ ABS ☐ Copper / Brass	
○ Satisfactory	cast iron leakage / damage / corrosion	inadequate slope
- ,	leakage / damage in drain pipe(s)	cleanout cap missing
	improper material / connections	improper installation
7 1		

	= Recommend a specialty contractor further inspect to determine all repair options and costs.
	#1 = Recommend qualified termite inspector #2 = Recommend qualified engineer \checkmark N/A = Not applicable \checkmark = Informational \checkmark Satisfactory = item exists and appears to function as it was designed to do
	Building Exterior (Continued)
14 Patio	Patio Room Patio Cover Open Patio Area Lattice type cover
Note: Patio covers and patio rooms are type portion of the premises.	pically required to have permits from the local municipality. Countywide makes no determination as to whether permits were acquired for any
Satisfactory	☐ patio slab has hairline cracks ☐ enclosure - damage / deterioration
☐ Rec. #1 #2	□ slab crack(s) – 1/16" - 1/8" - 1/4" - 1/2" or greater □ slab has improper slope for drainage □ electrical is improper / unsafe
♦ N/A	separation between slab & dwelling ungrounded outlet / reversed polarity
	□ patio slab covers stucco weepscreed or is within 2" □ no GFCl protection at the outlet(s) □ patio slab higher than/same as interior floor level □ exposed romex wiring
	slab covered by carpet - not evaluated slab covered by carpet - not evaluated possible burnt bulb(s)
	□ patio cover - roof damage / deterioration □ junction boxes not weatherproof □ structure appears to be overspanned □ improper conduit / connectors
	 □ structure appears to be overspanned □ structure has improper construction □ missing or damaged outlet / switch cover(s) □ missing or damaged outlet / switch cove
	weak connection at fascia board outlet(s) does not function
	□ damage at post bases □ glass windows don't conform to min. safety stnds. □ □ damage at post bases □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □
	
15 Deck / Balcony	
○ Satisfactory	deck damage / deterioration at step height uneven / improper rise & run balcony damage / deterioration: step(s) damaged / loose
☐ Rec. #1 #2	deck / balcony surface higher than/same as interior action railing too low / openings greater than 4" / missing
♦ N/A	no surface drain for balcony poor drainage / low spots railing damage / deterioration / loose hand railing not grippable
	deck / balcony framing deficient no GFCI protection at the outlet(s)
	improper material for use on a deck surface deck / balcony connection method not visible GFCI failed to respond properly exposed romex wiring
	☐ flashing deficiency at ledger ☐ possible burnt bulb(s)
	□ damage at post bases □ deck lacks proper post support □ missing covers for junction box(s) □ missing or damaged outlet / switch cover(s)
	☐ deck built on grade - subject to damage ☐ junction boxes not weatherproof
	earth to wood contact: improper conduit / connectors carpet hides deck surface
4	
_	
2	CONCRETE SLAB FOUNDATION
16 Slab-Exterior	Incomplete evaluation of perimeter foundation due to partially obstructed view (inaccessible - see below). Recommend subsequent reinspection after removal of obstruction.
○ Satisfactory	stucco to grade - unable to see slab edge spalling / flaking
☐ Rec. #1 #2	□ vertical crack(s) - hairline (see note below) □ reinforcing steel exposed / rusting
^	location weep screed covered by concrete vertical crack(s) - 1/16" - 1/8" - 1/4" - 1/2" or greater concrete within 2" of stucco weep screed
◇ N/A	location no apparent foundation / footing
	horizontal crack(s) location post tensioned cable ends exposed
	☐ efflorescence found (possible water intrusion) ☐ stem wall damage at anchor bolt locations
	due to:
<u> </u>	
Note: Concrete slabs with cracks noted at	the exterior slab edge should be evaluated by a qualified geo-technical engineer. Concrete slab edge cracks, even if within normal tolerances, may
	the integrity of the foundation. Evaluation of such cracks are beyond the scope of this inspection. Floor coverings prevent view of concrete floor surfaces - See Note below
^	☐ crack(s) - hairline (see note below) ☐ moisture / efflorescence (possible water intrusion)
○ Satisfactory ◇ N/A	location slope / unevenness
☐ Rec. #1 #2	crack(s) - 1/16" - 1/8" -1/4" - 1/2" or greater location warm floor - possible slab leak
<u> </u>	
Note: Concrete slabs usually are not visib	le at the interior due to floor coverings but often have some degree of surface cracking due to shrinkage. Slab cracks may not be detectable without
removal of the floor coverings. Whe inspector.	ther or not the inspector has detected cracks, you may wish to have floor coverings removed at your expense. Floor coverings are not removed by the

Bldg. Exterior / Foundation - Page 4

	Z Decreased a constitution of substitution in the delication.	and the section of th
	 = Recommend a specialty contractor further inspect to determine #1 = Recommend qualified termite inspector #2 = Recommend 	ne all repair options and costs. and qualified engineer $\langle \rangle$ N/A = Not applicable
	Satisfactory = item exists and ap	pears to function as it was designed to do
	RAISED FOUNDATION	
18 Foundation	Concrete Block Brick Piel	rs/Posts
○ Satisfactory	Access Location(s)	
☐ Rec. #1 #2	crack(s) - hairline (see note below) location	jacks have greater than 2" thread showing debris found in crawlspace
♦ N/A	☐ crack(s) - 1/16" - 1/8" -1/4" - 1/2" or greater location	older foundation - seismically vulnerable
•	horizontal crack(s)	foundation is unreinforced bricks / stones
	☐ reinforcing steel exposed / rusting	stem wall out of plumb
	spalling - moderate / severe	separation at marriage joint (m / h)evidence of rodent infestation
	☐ efflorescence on concrete stem wall / soils☐ rotation of the stem wall	strong musty odor
	evidence of wet soils / ponding water	crawlspace / underfloor areas were not
	ventilation may be inadequate / is blocked	inspected because: ☐ crawlspace access too small or blocked
	□ ventilation screens missing / damaged□ jacks were rusted / deteriorated	under floor clearance less than standard
	a jacks were rusted / deteriorated	under floor area blocked by pipes / ducts
☑ inaccessible area:	due to	D:
·	aluate concrete stern walls with cracks or deterioration. Stem wall cracks, even ation of the foregoing conditions is beyond the scope of this inspection.	if within normal tolerances, may have underlying conditions affecting
19 Framing	anchor bolts: yes / no not visible \diamondsuit N/A	
Satisfactory	wood framing stains	wood framing damp / wet
☐ Rec. #1 #2	■ wood framing damage / rot / cut■ missing / damaged posts / not centered on pier	anchor bolts loose tall walls not braced
♦ N/A	posts-piers not strapped	covered by insulation / vapor barrier
V N/A	□ loose posts	(framing not visible or inspected)
	wood / earth separation less than standard	overspanned joist or girder
_	ventilation less than standard	
Note: Anghar halfs ar attachment aveterna	often upper not installed during construction of clear between them EO upper them EO	so clall but are a standard of made as account ratios. Anabox balls balls
to secure the building to the foundati	often were not installed during construction of older homes (more than 50 year ion to prevent or minimize damage during earthquakes. If the inspector notes to the foundation of the construction of the foundation of the foundation of the foundation of the foundation.	
20 Plumbing / Ducts	nditions, you may wish to have a structural engineer evaluate the foundation. □ leakage at	_
○ Satisfactory ◇ N/A	damaged drain line (corrosion, rust)	gas pipe rusting / corrosion / leakage
	☐ damaged water supply line (corrosion, rust)☐ improper drain connections or fittings	sump pump (not tested). Check with homeowner about operation
☐ Rec. #1 #2	improper water supply line connections	ducts in contact with soil
	inadequate support for drain / water / gas line	duct insulation missing / damaged
	drain line has inadequate slope for drainage	disconnected or crushed ducts
21 Electrical	exposed wiring / open splices	needs proper wire connectors for junction box(s)
Satisfactory	open junction box(s)unsecured wiring (wires touching soil)	improper use of extension cord / lamp cord improper wiring
Rec. #1 #2	_ ancessed many (mass teastming early	— improper wining
<u>•</u>		
	ROOF	
22 Sloped	Type: Comp Shingle Wood Shake / S	hingle
	<u> </u>	rom ground - a limited and incomplete inspection
	oid damage; accordingly this is a limited inspection. Only a random sam advanced age / deterioration	pling of tiles are checked for attachment. □ cracked / broken tiles
Satisfactory□ Rec. #1 #2	☐ brittle or cracked shingles / shakes	☐ loose / missing tiles
□ Rec. #1 #2	missing shingles / shakes	holes in roof
♦ N/A	upping / curling shingles	improper pitch / slope
	☐ eroding surfaces at ridge / field	improper installation
	☐ felt paper is exposed / missing☐ felt paper is under edge metal☐	☐ patching / repairs noted☐ debris on roof
	exposed fasteners	protion of roof is sagging
	damaged wood sheathing / fascia / eaves	☐ 3" headlap not provided
	multiple layers (2+) installed	☐ tile not fastened to roof framing
	☐ tile laid over wood roof	☐ improper staggering of joints
inaccessible area:	due to	o:

	= Recommend a specialty contractor further inspect to determ	mine all repair options and costs.
		nend qualified engineer N/A = Not applicable appears to function as it was designed to do
		appears to function as it was designed to do
	Roof (Continued)	^
23 Low slope	Type: Gravel Rolled Foam	Single Ply Parapet walls
		r From ground - a limited and incomplete inspection
Satisfactory	advanced age / deteriorationcracking / blistering / split seams	patching / repairs notedexposed fasteners
☐ Rec. #1 #2	surface erosion / bare areas	metal edge is delaminating
♦ N/A	improper installation	☐ metal edge improperly installed
y iun	ponding / water stains	parapet walls are damaged
	no secondary drain on roofasphalt covering buckling / decomposed	debris on roof foam roof pitted / decomposed
	portion of roof is sagging	damage to metal roof covering
☑ inaccessible area:		
☐ Inaccessible area.	due	e to:
24 Flashing / Vents	roof jacks need sealing / repair	flashing / counter-flashing improper at
Satisfactory	roof jacks are not layered into roofing	skylight(s) at chimney
☐ Rec. #1 #2	☐ roof jacks improperly installed / missing	roof to wall joint not properly sealed
	mastic repairs (temporary repairs) at the jacks / skylights / roof to wall / roof surface / chimney / val	tile pans are missing / improper vent cap(s) missing / damaged
	valley is deteriorated / improperly installed	mortar plugs at vent pipe protrusions
	no counter flashing at house connection	wide chimney lacks cricket diverter
	□ valley flashing doesn't extend past roof edge	
25 Skylights		
○ Satisfactory ◇ N/A	☐ skylight installation sub-standard	☐ cracked / damaged cover
	urb is less than 4" above roof	skylight curbing too short
☐ Rec. #1 #2	ual glazed skylight - broken seal	sealant at skylight implies past leak
	wide skylight lacks cricket diversion	
	ATTIC	
26 Attic Framing		beams & planks
	ent leakage problem. This can only be determined with a water test of the roof, w. s of framing and electrical wiring; accordingly these areas are not inspected.	rhich is beyond the scope of the inspection. (ii) Insulation covering
Satisfactory	☐ no access located - contact Seller to confirm	joists appear to be overspanned
Satisfactory☐ Rec. #1 #2	☐ limited access - height / insulation / storage / duct	rafters appear to be overspanned
☐ Rec. #1 #2	☐ limited access - height / insulation / storage / duct ☐ attic access hatch missing / damaged	rafters appear to be overspanned chimney straps are not attached
_	☐ limited access - height / insulation / storage / duct	rafters appear to be overspanned
☐ Rec. #1 #2	☐ limited access - height / insulation / storage / duct ☐ attic access hatch missing / damaged ☐ truss is broken / damaged / cut / altered ☐ joist / rafter is damaged / cut / altered	rafters appear to be overspanned chimney straps are not attached draft stop not installed around chimney
☐ Rec. #1 #2	☐ limited access - height / insulation / storage / duct ☐ attic access hatch missing / damaged ☐ truss is broken / damaged / cut / altered ☐ joist / rafter is damaged / cut / altered	rafters appear to be overspanned chimney straps are not attached draft stop not installed around chimney stains on underside of roof
Rec. #1 #2 N/A inaccessible area:	☐ limited access - height / insulation / storage / duct ☐ attic access hatch missing / damaged ☐ truss is broken / damaged / cut / altered ☐ joist / rafter is damaged / cut / altered	rafters appear to be overspanned chimney straps are not attached draft stop not installed around chimney stains on underside of roof
Rec. #1 #2 N/A inaccessible area: Attic Ventilation	□ limited access - height / insulation / storage / duct □ attic access hatch missing / damaged □ truss is broken / damaged / cut / altered □ joist / rafter is damaged / cut / altered □ due	rafters appear to be overspanned chimney straps are not attached draft stop not installed around chimney stains on underside of roof to: Turbines Electric fan screens are missing / rusted through
Rec. #1 #2 N/A inaccessible area: Attic Ventilation Satisfactory	□ limited access - height / insulation / storage / duct □ attic access hatch missing / damaged □ truss is broken / damaged / cut / altered □ joist / rafter is damaged / cut / altered □ due	rafters appear to be overspanned chimney straps are not attached draft stop not installed around chimney stains on underside of roof to: Turbines Electric fan
Rec. #1 #2 N/A inaccessible area: Attic Ventilation Satisfactory	□ limited access - height / insulation / storage / duct □ attic access hatch missing / damaged □ truss is broken / damaged / cut / altered □ joist / rafter is damaged / cut / altered □ due □ Gable □ Freize block □ Soffit □ Dormers □ ventilation - none observed / inadequate	rafters appear to be overspanned chimney straps are not attached draft stop not installed around chimney stains on underside of roof to: Turbines Electric fan screens are missing / rusted through
Rec. #1 #2 N/A inaccessible area: Attic Ventilation Satisfactory	□ limited access - height / insulation / storage / duct □ attic access hatch missing / damaged □ truss is broken / damaged / cut / altered □ joist / rafter is damaged / cut / altered □ due □ Gable □ Freize block □ Soffit □ Dormers □ ventilation - none observed / inadequate □ ventilation - screen(s) blocked	rafters appear to be overspanned chimney straps are not attached draft stop not installed around chimney stains on underside of roof to: Turbines Electric fan screens are missing / rusted through electric fan not functional / not tested
Rec. #1 #2 N/A inaccessible area: Attic Ventilation Satisfactory	□ limited access - height / insulation / storage / duct □ attic access hatch missing / damaged □ truss is broken / damaged / cut / altered □ joist / rafter is damaged / cut / altered □ due □ Gable □ Freize block □ Soffit □ Dormers □ ventilation - none observed / inadequate □ ventilation - screen(s) blocked □ Thickness □ □ Batts □ Loose fill	rafters appear to be overspanned chimney straps are not attached draft stop not installed around chimney stains on underside of roof to: Turbines Electric fan screens are missing / rusted through electric fan not functional / not tested
Rec. #1 #2 N/A inaccessible area: Attic Ventilation Satisfactory	□ limited access - height / insulation / storage / duct □ attic access hatch missing / damaged □ truss is broken / damaged / cut / altered □ joist / rafter is damaged / cut / altered □ due □ due □ ventilation - none observed / inadequate □ ventilation - screen(s) blocked □ hickness □ Batts □ Loose fill □ none / inadequate insulation - (less than 6")	rafters appear to be overspanned chimney straps are not attached draft stop not installed around chimney stains on underside of roof to: Turbines Electric fan screens are missing / rusted through electric fan not functional / not tested insulation covers knob and tube wiring
Rec. #1 #2 N/A inaccessible area: Attic Ventilation Satisfactory Attic Insulation	□ limited access - height / insulation / storage / duct □ attic access hatch missing / damaged □ truss is broken / damaged / cut / altered □ joist / rafter is damaged / cut / altered □ due □ due □ ventilation - none observed / inadequate □ ventilation - screen(s) blocked □ hone / inadequate insulation - (less than 6") □ areas missing insulation	rafters appear to be overspanned chimney straps are not attached draft stop not installed around chimney stains on underside of roof to: Turbines Electric fan screens are missing / rusted through electric fan not functional / not tested insulation covers knob and tube wiring insulation covers lights / vents
Rec. #1 #2 N/A inaccessible area: Attic Ventilation Satisfactory Attic Insulation	□ limited access - height / insulation / storage / duct □ attic access hatch missing / damaged □ truss is broken / damaged / cut / altered □ joist / rafter is damaged / cut / altered □ due □ due □ ventilation - none observed / inadequate □ ventilation - screen(s) blocked □ hickness □ Batts □ Loose fill □ none / inadequate insulation - (less than 6")	rafters appear to be overspanned chimney straps are not attached draft stop not installed around chimney stains on underside of roof to: Turbines Electric fan screens are missing / rusted through electric fan not functional / not tested insulation covers knob and tube wiring
Rec. #1 #2 N/A inaccessible area: The reconstruction Satisfactory Attic Insulation Satisfactory Satisfactory Satisfactory	□ limited access - height / insulation / storage / duct □ attic access hatch missing / damaged □ truss is broken / damaged / cut / altered □ joist / rafter is damaged / cut / altered □ due □ due □ Ventilation - none observed / inadequate □ ventilation - screen(s) blocked □ none / inadequate insulation - (less than 6") □ areas missing insulation □ insulation is deteriorated in areas	rafters appear to be overspanned chimney straps are not attached draft stop not installed around chimney stains on underside of roof to: Turbines Electric fan screens are missing / rusted through electric fan not functional / not tested insulation covers knob and tube wiring insulation covers lights / vents insulation falling / hanging from walls
Rec. #1 #2 N/A inaccessible area: Attic Ventilation Satisfactory Attic Insulation Satisfactory Satisfactory	□ limited access - height / insulation / storage / duct □ attic access hatch missing / damaged □ truss is broken / damaged / cut / altered □ joist / rafter is damaged / cut / altered □ due □ due □ Ventilation - none observed / inadequate □ ventilation - screen(s) blocked □ none / inadequate insulation - (less than 6") □ areas missing insulation □ insulation is deteriorated in areas	rafters appear to be overspanned chimney straps are not attached draft stop not installed around chimney stains on underside of roof to: Turbines Electric fan screens are missing / rusted through electric fan not functional / not tested insulation covers knob and tube wiring insulation covers lights / vents insulation falling / hanging from walls evidence of rodent activity
Rec. #1 #2 N/A inaccessible area: Attic Ventilation Satisfactory Attic Insulation Satisfactory Satisfactory	□ limited access - height / insulation / storage / duct □ attic access hatch missing / damaged □ truss is broken / damaged / cut / altered □ joist / rafter is damaged / cut / altered □ due □ due □ due □ ventilation - none observed / inadequate □ ventilation - screen(s) blocked □ none / inadequate insulation - (less than 6") □ areas missing insulation □ insulation is deteriorated in areas □ attic insulated w/ non-standard materials	rafters appear to be overspanned chimney straps are not attached draft stop not installed around chimney stains on underside of roof to: Turbines Electric fan screens are missing / rusted through electric fan not functional / not tested insulation covers knob and tube wiring insulation covers lights / vents insulation falling / hanging from walls evidence of rodent activity insulation installed incorrectly
Rec. #1 #2 N/A inaccessible area: Attic Ventilation Satisfactory Attic Insulation Satisfactory Attic Insulation Attic Wiring	□ limited access - height / insulation / storage / duct □ attic access hatch missing / damaged □ truss is broken / damaged / cut / altered □ joist / rafter is damaged / cut / altered □ due □ due □ due □ ventilation - none observed / inadequate □ ventilation - screen(s) blocked □ hone / inadequate insulation - (less than 6") □ areas missing insulation □ insulation is deteriorated in areas □ attic insulated w/ non-standard materials □ Romex □ Conduit □ Flex conduit □ K	rafters appear to be overspanned chimney straps are not attached draft stop not installed around chimney stains on underside of roof to: Turbines Electric fan screens are missing / rusted through electric fan not functional / not tested insulation covers knob and tube wiring insulation covers lights / vents insulation falling / hanging from walls evidence of rodent activity insulation installed incorrectly
Rec. #1 #2 N/A inaccessible area: Attic Ventilation Satisfactory Attic Insulation Satisfactory Satisfactory	□ limited access - height / insulation / storage / duct □ attic access hatch missing / damaged □ truss is broken / damaged / cut / altered □ joist / rafter is damaged / cut / altered □ due □ due □ due □ ventilation - none observed / inadequate □ ventilation - screen(s) blocked □ none / inadequate insulation - (less than 6") □ areas missing insulation □ insulation is deteriorated in areas □ attic insulated w/ non-standard materials	rafters appear to be overspanned chimney straps are not attached draft stop not installed around chimney stains on underside of roof to: Turbines Electric fan screens are missing / rusted through electric fan not functional / not tested insulation covers knob and tube wiring insulation covers lights / vents insulation falling / hanging from walls evidence of rodent activity insulation installed incorrectly Inob & Tube tc. knob & tubing wiring - older type wiring system - recommend evaluation
Rec. #1 #2 N/A inaccessible area: Attic Ventilation Satisfactory Attic Insulation Satisfactory Attic Insulation Attic Wiring	□ limited access - height / insulation / storage / duct □ attic access hatch missing / damaged □ truss is broken / damaged / cut / altered □ joist / rafter is damaged / cut / altered □ due □ due □ due □ ventilation - none observed / inadequate □ ventilation - screen(s) blocked □ none / inadequate insulation - (less than 6") □ areas missing insulation □ insulation is deteriorated in areas □ attic insulated w/ non-standard materials □ Romex □ Conduit □ Flex conduit □ K □ limited view of wiring due to insulation, storage, et	rafters appear to be overspanned chimney straps are not attached draft stop not installed around chimney stains on underside of roof to: Turbines Electric fan screens are missing / rusted through electric fan not functional / not tested insulation covers knob and tube wiring insulation covers lights / vents insulation falling / hanging from walls evidence of rodent activity insulation installed incorrectly tc. knob & tubing wiring - older type wiring system - recommend evaluation open junction boxes need covers
Rec. #1 #2 N/A inaccessible area: Attic Ventilation Satisfactory Attic Insulation Satisfactory Attic Insulation Attic Wiring	□ limited access - height / insulation / storage / duct □ attic access hatch missing / damaged □ truss is broken / damaged / cut / altered □ joist / rafter is damaged / cut / altered □ due □ due □ due □ due □ ventilation - none observed / inadequate □ ventilation - screen(s) blocked □ none / inadequate insulation - (less than 6") □ areas missing insulation □ insulation is deteriorated in areas □ attic insulated w/ non-standard materials □ Romex □ Conduit □ Flex conduit □ K □ limited view of wiring due to insulation, storage, etc. □ exposed wiring (e.g. open splices) □ improper wiring (extension cord) □ needs proper wire connectors for junction box(s)	rafters appear to be overspanned chimney straps are not attached draft stop not installed around chimney stains on underside of roof to: Turbines Electric fan screens are missing / rusted through electric fan not functional / not tested insulation covers knob and tube wiring insulation falling / hanging from walls evidence of rodent activity insulation installed incorrectly Inob & Tube tc. knob & tubing wiring - older type wiring system - recommend evaluation open junction boxes need covers multiple instances of improper wiring
Rec. #1 #2 N/A inaccessible area: Attic Ventilation Satisfactory Attic Insulation Satisfactory Attic Insulation Attic Wiring	□ limited access - height / insulation / storage / duct □ attic access hatch missing / damaged □ truss is broken / damaged / cut / altered □ joist / rafter is damaged / cut / altered □ due □ due □ ventilation - none observed / inadequate □ ventilation - screen(s) blocked □ none / inadequate insulation - (less than 6") □ areas missing insulation □ insulation is deteriorated in areas □ attic insulated w/ non-standard materials □ Romex □ Conduit □ Flex conduit □ K □ limited view of wiring due to insulation, storage, etc. □ exposed wiring (e.g. open splices) □ improper wiring (extension cord)	rafters appear to be overspanned chimney straps are not attached draft stop not installed around chimney stains on underside of roof to: Turbines Electric fan screens are missing / rusted through electric fan not functional / not tested insulation covers knob and tube wiring insulation covers lights / vents insulation falling / hanging from walls evidence of rodent activity insulation installed incorrectly tc. knob & tubing wiring - older type wiring system - recommend evaluation open junction boxes need covers

	= Recommend a specialty contractor further inspect to determine						
	#1 = Recommend qualified termite inspector #2 = Recommend qualified engineer N/A = Not applicable 1 = Recommend qualified termite inspector #2 = Recommend qualified engineer N/A = Not applicable 2 = Informational						
		sals to full clion as it was designed to do					
	ATTIC (Continued)						
30 HVAC Ducts / Venting	disconnected or crushed ducts						
○ Satisfactory	disconnected or crushed ducts duct insulation missing / damaged	✓ vent pipe has improper slope✓ vent pipe has gaps at joints					
	inadequate clearance of vent pipe to combustibles	vent pipe has gaps at joints vent pipe damaged / improperly secured					
	☐ improper materials for vent pipe	✓ vent pipe damaged / improperty secured					
<u> </u>							
31 Attic Plumbing							
○ Satisfactory	improper drain line connection	improper slope for drain line					
Rec. #1 #2	□ bath / kitchen vent doesn't extend thru roof□ inadequate support of drain / water pipe	☐ leakage in attic plumbing☐ damaged water / drain pipe					
	inadequate support of drain / water pipe	damaged water / drain pipe					
<u> </u>							
	OARAGE						
	GARAGE						
Roof Underside / Framing		ype See roof note at section 22 of this report.					
○ Satisfactory	☐ garage not inspected - too many stored items☐ damage / deterioration to underside of roof	siding damage / deterioration non-moisture damage at wall					
☐ Rec. #1 #2	water stains at underside of roof	sagging beam over vehicle door					
♦ N/A	☐ water stains at ceiling / walls	roof rafters cut / broken / cracked					
·	framing improper at door / window / storage	awning deficient - post / frame / cover					
_	framing damage / deterioration	arport post / frame is deficient					
	due to:						
33 Slab / Foundation	garage not inspected - too many stored items	☐ slab separation at foundation stem wall ☐ hairline foundation stem wall cracks					
Satisfactory	slab cracks - hairline slab cracks - 1/16" - 1/8" - 1/4" - 1/2" or greater	☐ foundation stem wall cracks -					
☐ Rec. #1 #2	excessive number of slab cracks	1/16" - 1/8" - 1/4" - 1/2" or greater evidence of spalling (chiping/flaking) at foundation					
	☐ efflorescence found - floor / stem walls	slab floor improperly sloping or uneven					
inaccessible area:	due to:						
<u> </u>							
34 Fire Door	improper type for firedoor - not 1 3/8" solid core / window / pet door	self closer missing or disconnected					
Satisfactory	damage / deterioration	☐ firedoor opens into a bedroom ☐ firedoor is not tight fitting					
☐ Rec. #1 #2	☐ threshold missing at fire door						
<u></u>							
35 Fire Wall	☐ holes / damage in fire wall or ceiling	plastic dryer vent violates firewall					
	no firewall installed	☐ furnace / WH platform needs firewall					
○ Satisfactory	improper material for firewall	☐ furnace duct violates firewall					
☐ Rec. #1 #2	ceiling opening may not conform						
36 Door / Window	moisture damage - door to exterior	uindow lockset / latch in disrepair / missing					
○ Satisfactory ◇ N/A	non moisture damage to door	window does not function properly					
☐ Rec. #1 #2	stains or leakage at door door binds against jamb	window screen is missing / damaged					
<u> </u>	door binds against jamb door lockset / latch in disrepair / missing	glass is cracked / broken window frame damage (moisture / non-moisture)					
	door opens over step w/out a landing	□ evidence of leakage at window sill					
	glass in door not safety tempered	dual glazed window seal broken					
<u> </u>							
37 Garage Door	damage / deterioration / rot	☐ springs are broken / rusted					
○ Satisfactory	tension rods loose / missing	springs are improper type					
Rec. #1 #2	tension bar bridge is missing	non-safety type springs					
- NGO. #1 #2	hinges damaged / non-approved partsdoor springs in need of adjustment	☐ non-safety type spring attachment ☐ door is locked / blocked - not tested					
	broken components - door not tested	door is locked / blocked - not tested					
	•						

	= Recommend a specialty contractor further inspect to determin	^
		d qualified engineer N/A = Not applicable pears to function as it was designed to do
	GARAGE (Continued)	<u> </u>
38 Garage Door Opener	not tested	does not have automatic reverse
	not functional	does not conform to current standards
Satisfactory	needs adjustment	improper wiring (extension cord)
☐ Rec. #1 #2	electronic sensor not within 6" from floor	□ vehicle door lacks safety sensors
	•	
39 Ventilation	☐ blocked vents	vent screens damaged / missing
	ventilation lacking in garage	Tolk soles damaged, missing
○ Satisfactory		
Rec. #1 #2		. —
40 Electrical	wiring mounted less than 7' is not protected	ungrounded outlet(s)
○ Satisfactory	overhead wiring spans open spaces / not secured	reversed polarity at outlet(s)
☐ Rec. #1 #2	exposed wiring / open splicesextension cord used for lights / wiring	no GFCI at outlet(s)GFCI failed to respond properly to test
	missing or damaged outlet / switch cover(s)	open junction box(s)
	needs proper wire connectors for junction box(s)	utlet does not function
	,	
41 Misc. Garage Comments	musty odor in garagegarage converted - no covered parking	step treads / risers not uniform
○ Satisfactory	garage converted - no covered parking garage appears to have been carport	openings in railings too wide garage stairs potentially unsafe
☐ Rec. #1 #2	steps from house to garage needs handrail	garage stairs potentially unsafe
	The state of the s	
_	LAUNDRY	
42 Laundry Plumbing	☐ Laundry Room ☐ Garage ☐ Hall ☐ Bathroom	Patio Exterior
Satisfactory	Washer: Laundry sink	Dryer:
Jalisiaciory		sink drain line leaks / slow to drain
NI/A	washer hookup(s) leaking - H / C	\square Silik dialif life leaks / Slow to dialif
◇ N/A	□ washer hookup(s) leaking - H / C□ washer supply valve corroded / leaking - H / C	sink drain line leaks / slow to drain
Note: Laundry machines		
	□ washer supply valve corroded / leaking - H / C □ sink faucet corroded / leaks □ sink faucet valve(s) corroded / leaks - H / C	sink / washer faucet handle corroded / missing improper drain / vent / trap sink not securely fastened / damaged
Note: Laundry machines and laundry valves	□ washer supply valve corroded / leaking - H / C □ sink faucet corroded / leaks	sink / washer faucet handle corroded / missing improper drain / vent / trap sink not securely fastened / damaged no shut-off valves at washer supply
Note: Laundry machines and laundry valves	□ washer supply valve corroded / leaking - H / C □ sink faucet corroded / leaks □ sink faucet valve(s) corroded / leaks - H / C	sink / washer faucet handle corroded / missing improper drain / vent / trap sink not securely fastened / damaged
Note: Laundry machines and laundry valves are not tested.	□ washer supply valve corroded / leaking - H / C □ sink faucet corroded / leaks □ sink faucet valve(s) corroded / leaks - H / C	sink / washer faucet handle corroded / missing improper drain / vent / trap sink not securely fastened / damaged no shut-off valves at washer supply
Note: Laundry machines and laundry valves are not tested.	□ washer supply valve corroded / leaking - H / C □ sink faucet corroded / leaks □ sink faucet valve(s) corroded / leaks - H / C	sink / washer faucet handle corroded / missing improper drain / vent / trap sink not securely fastened / damaged no shut-off valves at washer supply
Note: Laundry machines and laundry valves are not tested. Appliance Electrical	washer supply valve corroded / leaking - H / C sink faucet corroded / leaks sink faucet valve(s) corroded / leaks - H / C sink supply valve corroded / leaks - H / C	sink / washer faucet handle corroded / missing improper drain / vent / trap sink not securely fastened / damaged no shut-off valves at washer supply hook-ups not visible (not inspected)
Note: Laundry machines and laundry valves are not tested. Appliance Electrical Satisfactory	washer supply valve corroded / leaking - H / C sink faucet corroded / leaks sink faucet valve(s) corroded / leaks - H / C sink supply valve corroded / leaks - H / C no 240 volt outlet was located no power to 240 volt outlet 240 volt outlet not accessible - (not tested)	sink / washer faucet handle corroded / missing improper drain / vent / trap sink not securely fastened / damaged no shut-off valves at washer supply hook-ups not visible (not inspected)
Note: Laundry machines and laundry valves are not tested. Appliance Electrical Satisfactory N/A	washer supply valve corroded / leaking - H / C sink faucet corroded / leaks sink faucet valve(s) corroded / leaks - H / C sink supply valve corroded / leaks - H / C no 240 volt outlet was located no power to 240 volt outlet	sink / washer faucet handle corroded / missing improper drain / vent / trap sink not securely fastened / damaged no shut-off valves at washer supply hook-ups not visible (not inspected) 240 volt outlet loose
Note: Laundry machines and laundry valves are not tested. Appliance Electrical Satisfactory	washer supply valve corroded / leaking - H / C sink faucet corroded / leaks sink faucet valve(s) corroded / leaks - H / C sink supply valve corroded / leaks - H / C no 240 volt outlet was located no power to 240 volt outlet 240 volt outlet not accessible - (not tested)	sink / washer faucet handle corroded / missing improper drain / vent / trap sink not securely fastened / damaged no shut-off valves at washer supply hook-ups not visible (not inspected)
Note: Laundry machines and laundry valves are not tested. Appliance Electrical Satisfactory N/A	washer supply valve corroded / leaking - H / C sink faucet corroded / leaks sink faucet valve(s) corroded / leaks - H / C sink supply valve corroded / leaks - H / C no 240 volt outlet was located no power to 240 volt outlet 240 volt outlet not accessible - (not tested)	sink / washer faucet handle corroded / missing improper drain / vent / trap sink not securely fastened / damaged no shut-off valves at washer supply hook-ups not visible (not inspected)
Note: Laundry machines and laundry valves are not tested. 43 Appliance Electrical Satisfactory N/A Dryer Gas Line / Vent	washer supply valve corroded / leaking - H / C sink faucet corroded / leaks sink faucet valve(s) corroded / leaks - H / C sink supply valve corroded / leaks - H / C no 240 volt outlet was located no power to 240 volt outlet 240 volt outlet not accessible - (not tested) 240 volt outlet damaged / improper / missing cover gas supply was shut down left gas line routed thru wall	sink / washer faucet handle corroded / missing improper drain / vent / trap sink not securely fastened / damaged no shut-off valves at washer supply hook-ups not visible (not inspected) 240 volt outlet loose 240 volt outlet loose dull back draft damper missing / damaged duct separated / disconnected
Note: Laundry machines and laundry valves are not tested. 43 Appliance Electrical Satisfactory N/A 44 Dryer Gas Line / Vent Satisfactory	washer supply valve corroded / leaking - H / C sink faucet corroded / leaks sink faucet valve(s) corroded / leaks - H / C sink supply valve corroded / leaks - H / C no 240 volt outlet was located no power to 240 volt outlet 240 volt outlet not accessible - (not tested) 240 volt outlet damaged / improper / missing cover gas supply was shut down flex gas line routed thru wall improper gas connection	sink / washer faucet handle corroded / missing improper drain / vent / trap sink not securely fastened / damaged no shut-off valves at washer supply hook-ups not visible (not inspected) 240 volt outlet loose 240 volt outlet loose duble damaged duct separated / disconnected flex dryer duct exceeds 6'
Note: Laundry machines and laundry valves are not tested. 43 Appliance Electrical Satisfactory N/A Dryer Gas Line / Vent	washer supply valve corroded / leaking - H / C sink faucet corroded / leaks sink faucet valve(s) corroded / leaks - H / C sink supply valve corroded / leaks - H / C no 240 volt outlet was located no power to 240 volt outlet 240 volt outlet not accessible - (not tested) 240 volt outlet damaged / improper / missing cover gas supply was shut down flex gas line routed thru wall improper gas connection dryer does not vent to exterior	sink / washer faucet handle corroded / missing improper drain / vent / trap sink not securely fastened / damaged no shut-off valves at washer supply hook-ups not visible (not inspected) 240 volt outlet loose 240 volt outlet loose disconnected flex dryer duct exceeds 6' odor of gas - needs immediate evaluation
Note: Laundry machines and laundry valves are not tested. 43 Appliance Electrical Satisfactory N/A 44 Dryer Gas Line / Vent Satisfactory N/A	washer supply valve corroded / leaking - H / C sink faucet corroded / leaks sink faucet valve(s) corroded / leaks - H / C sink supply valve corroded / leaks - H / C no 240 volt outlet was located no power to 240 volt outlet 240 volt outlet not accessible - (not tested) 240 volt outlet damaged / improper / missing cover gas supply was shut down flex gas line routed thru wall improper gas connection	sink / washer faucet handle corroded / missing improper drain / vent / trap sink not securely fastened / damaged no shut-off valves at washer supply hook-ups not visible (not inspected) 240 volt outlet loose 240 volt outlet loose duble damaged duct separated / disconnected flex dryer duct exceeds 6'
Note: Laundry machines and laundry valves are not tested. 43 Appliance Electrical Satisfactory N/A 44 Dryer Gas Line / Vent Satisfactory	washer supply valve corroded / leaking - H / C sink faucet corroded / leaks sink faucet valve(s) corroded / leaks - H / C sink supply valve corroded / leaks - H / C no 240 volt outlet was located no power to 240 volt outlet 240 volt outlet not accessible - (not tested) 240 volt outlet damaged / improper / missing cover gas supply was shut down flex gas line routed thru wall improper gas connection dryer does not vent to exterior	sink / washer faucet handle corroded / missing improper drain / vent / trap sink not securely fastened / damaged no shut-off valves at washer supply hook-ups not visible (not inspected) 240 volt outlet loose 240 volt outlet loose disconnected flex dryer duct exceeds 6' odor of gas - needs immediate evaluation
Note: Laundry machines and laundry valves are not tested. 43 Appliance Electrical Satisfactory N/A 44 Dryer Gas Line / Vent Satisfactory N/A	washer supply valve corroded / leaking - H / C sink faucet corroded / leaks sink faucet valve(s) corroded / leaks - H / C sink supply valve corroded / leaks - H / C no 240 volt outlet was located no power to 240 volt outlet 240 volt outlet not accessible - (not tested) 240 volt outlet damaged / improper / missing cover gas supply was shut down flex gas line routed thru wall improper gas connection dryer does not vent to exterior no provision for venting of dryer	sink / washer faucet handle corroded / missing improper drain / vent / trap sink not securely fastened / damaged no shut-off valves at washer supply hook-ups not visible (not inspected) 240 volt outlet loose 240 volt outlet loose disconnected flex dryer duct exceeds 6' odor of gas - needs immediate evaluation
Note: Laundry machines and laundry valves are not tested. 43 Appliance Electrical Satisfactory N/A 44 Dryer Gas Line / Vent Satisfactory N/A Rec. #1 #2	washer supply valve corroded / leaking - H / C sink faucet corroded / leaks sink faucet valve(s) corroded / leaks - H / C sink supply valve corroded / leaks - H / C no 240 volt outlet was located no power to 240 volt outlet 240 volt outlet not accessible - (not tested) 240 volt outlet damaged / improper / missing cover gas supply was shut down flex gas line routed thru wall improper gas connection dryer does not vent to exterior no provision for venting of dryer s c N/A	sink / washer faucet handle corroded / missing improper drain / vent / trap sink not securely fastened / damaged no shut-off valves at washer supply hook-ups not visible (not inspected) 240 volt outlet loose back draft damper missing / damaged duct separated / disconnected flex dryer duct exceeds 6' odor of gas - needs immediate evaluation
Note: Laundry machines and laundry valves are not tested. 43 Appliance Electrical Satisfactory N/A 44 Dryer Gas Line / Vent Satisfactory N/A Rec. #1 #2 45 Floor	washer supply valve corroded / leaking - H / C sink faucet corroded / leaks sink faucet valve(s) corroded / leaks - H / C sink supply valve corroded / leaks - H / C no 240 volt outlet was located no power to 240 volt outlet 240 volt outlet not accessible - (not tested) 240 volt outlet damaged / improper / missing cover gas supply was shut down flex gas line routed thru wall improper gas connection dryer does not vent to exterior no provision for venting of dryer s c N/A	sink / washer faucet handle corroded / missing improper drain / vent / trap sink not securely fastened / damaged no shut-off valves at washer supply hook-ups not visible (not inspected) 240 volt outlet loose back draft damper missing / damaged duct separated / disconnected flex dryer duct exceeds 6' odor of gas - needs immediate evaluation
Note: Laundry machines and laundry valves are not tested. 43 Appliance Electrical Satisfactory N/A 44 Dryer Gas Line / Vent Satisfactory N/A Rec. #1 #2 45 Floor 46 Walls	washer supply valve corroded / leaking - H / C sink faucet corroded / leaks sink faucet valve(s) corroded / leaks - H / C sink supply valve corroded / leaks - H / C no 240 volt outlet was located no power to 240 volt outlet 240 volt outlet not accessible - (not tested) 240 volt outlet damaged / improper / missing cover gas supply was shut down flex gas line routed thru wall improper gas connection dryer does not vent to exterior no provision for venting of dryer s c N/A stains / discoloration / patching / damage	sink / washer faucet handle corroded / missing improper drain / vent / trap sink not securely fastened / damaged no shut-off valves at washer supply hook-ups not visible (not inspected) 240 volt outlet loose back draft damper missing / damaged duct separated / disconnected flex dryer duct exceeds 6' odor of gas - needs immediate evaluation de / cracks - hairline / 1/16" / 1/8" / 1/8"+ / numerous
Note: Laundry machines and laundry valves are not tested. 43 Appliance Electrical Satisfactory N/A 44 Dryer Gas Line / Vent Satisfactory N/A Rec. #1 #2 45 Floor 46 Walls 47 Ceiling	washer supply valve corroded / leaking - H / C sink faucet corroded / leaks sink faucet valve(s) corroded / leaks - H / C sink supply valve corroded / leaks - H / C no 240 volt outlet was located no power to 240 volt outlet 240 volt outlet not accessible - (not tested) 240 volt outlet damaged / improper / missing cover gas supply was shut down flex gas line routed thru wall improper gas connection dryer does not vent to exterior no provision for venting of dryer s c N/A stains / discoloration / patching / damaged is stains / discoloration / patching / damaged / damaged is stains / discoloration / patching / damaged / dam	sink / washer faucet handle corroded / missing improper drain / vent / trap sink not securely fastened / damaged no shut-off valves at washer supply hook-ups not visible (not inspected) 240 volt outlet loose back draft damper missing / damaged duct separated / disconnected flex dryer duct exceeds 6' odor of gas - needs immediate evaluation
Note: Laundry machines and laundry valves are not tested. 43 Appliance Electrical Satisfactory N/A 44 Dryer Gas Line / Vent Satisfactory N/A Rec. #1 #2 45 Floor 46 Walls 47 Ceiling 48 Doors	washer supply valve corroded / leaking - H / C sink faucet corroded / leaks sink faucet valve(s) corroded / leaks - H / C sink supply valve corroded / leaks - H / C sink supply valve corroded / leaks - H / C no 240 volt outlet was located no power to 240 volt outlet 240 volt outlet not accessible - (not tested) 240 volt outlet damaged / improper / missing cover gas supply was shut down flex gas line routed thru wall improper gas connection dryer does not vent to exterior no provision for venting of dryer s c N/A stains / discoloration / patching / damaged hardware missing / damaged	sink / washer faucet handle corroded / missing improper drain / vent / trap sink not securely fastened / damaged no shut-off valves at washer supply hook-ups not visible (not inspected) 240 volt outlet loose back draft damper missing / damaged duct separated / disconnected flex dryer duct exceeds 6' odor of gas - needs immediate evaluation de / cracks - hairline / 1/16" / 1/8" / 1/8"+ / numerous
Note: Laundry machines and laundry valves are not tested. 43 Appliance Electrical Satisfactory N/A 44 Dryer Gas Line / Vent Satisfactory N/A Rec. #1 #2 45 Floor 46 Walls 47 Ceiling 48 Doors 49 Windows	□ washer supply valve corroded / leaking - H / C □ sink faucet corroded / leaks □ sink faucet valve(s) corroded / leaks - H / C □ sink supply valve corroded / leaks - H / C □ sink supply valve corroded / leaks - H / C □ no power to 240 volt outlet □ 240 volt outlet not accessible - (not tested) □ 240 volt outlet damaged / improper / missing cover □ gas supply was shut down □ flex gas line routed thru wall □ improper gas connection □ dryer does not vent to exterior □ no provision for venting of dryer s c N/A □ □ □ stains / discoloration / patching / damaged □ □ streens - damaged / missing	sink / washer faucet handle corroded / missing improper drain / vent / trap sink not securely fastened / damaged no shut-off valves at washer supply hook-ups not visible (not inspected) 240 volt outlet loose back draft damper missing / damaged duct separated / disconnected flex dryer duct exceeds 6' odor of gas - needs immediate evaluation of cracks - hairline / 1/16" / 1/8" / 1/8"+ / numerous ge / cracks - hairline / 1/16" / 1/8" / 1/8"+ / numerous
Note: Laundry machines and laundry valves are not tested. 43 Appliance Electrical Satisfactory N/A 44 Dryer Gas Line / Vent Satisfactory N/A Rec. #1 #2 45 Floor 46 Walls 47 Ceiling 48 Doors	washer supply valve corroded / leaking - H / C sink faucet corroded / leaks sink faucet valve(s) corroded / leaks - H / C sink supply valve corroded / leaks - H / C sink supply valve corroded / leaks - H / C no 240 volt outlet was located no power to 240 volt outlet 240 volt outlet not accessible - (not tested) 240 volt outlet damaged / improper / missing cover gas supply was shut down flex gas line routed thru wall improper gas connection dryer does not vent to exterior no provision for venting of dryer s c N/A stains / discoloration / patching / damaged hardware missing / damaged hardware missing / damaged screens - damaged / missing	sink / washer faucet handle corroded / missing improper drain / vent / trap sink not securely fastened / damaged no shut-off valves at washer supply hook-ups not visible (not inspected) 240 volt outlet loose back draft damper missing / damaged duct separated / disconnected flex dryer duct exceeds 6' odor of gas - needs immediate evaluation of cracks - hairline / 1/16" / 1/8" / 1/8"+ / numerous ge / cracks - hairline / 1/16" / 1/8" / 1/8"+ / numerous
Note: Laundry machines and laundry valves are not tested. 43 Appliance Electrical Satisfactory N/A 44 Dryer Gas Line / Vent Satisfactory N/A Rec. #1 #2 45 Floor 46 Walls 47 Ceiling 48 Doors 49 Windows 50 Electrical 51 Cabinets / Closets	washer supply valve corroded / leaking - H / C sink faucet corroded / leaks sink faucet valve(s) corroded / leaks - H / C sink supply valve corroded / leaks - H / C sink supply valve corroded / leaks - H / C no 240 volt outlet was located no power to 240 volt outlet 240 volt outlet not accessible - (not tested) 240 volt outlet damaged / improper / missing cover gas supply was shut down flex gas line routed thru wall improper gas connection dryer does not vent to exterior no provision for venting of dryer s c N/A s c N/A s c N/A s c	sink / washer faucet handle corroded / missing improper drain / vent / trap sink not securely fastened / damaged no shut-off valves at washer supply hook-ups not visible (not inspected) 240 volt outlet loose back draft damper missing / damaged duct separated / disconnected flex dryer duct exceeds 6' odor of gas - needs immediate evaluation of cracks - hairline / 1/16" / 1/8" / 1/8"+ / numerous ge / cracks - hairline / 1/16" / 1/8" / 1/8"+ / numerous
Note: Laundry machines and laundry valves are not tested. 43 Appliance Electrical Satisfactory N/A 44 Dryer Gas Line / Vent Satisfactory N/A Rec. #1 #2 45 Floor 46 Walls 47 Ceiling 48 Doors 49 Windows 50 Electrical 51 Cabinets / Closets	washer supply valve corroded / leaking - H / C sink faucet corroded / leaks sink faucet valve(s) corroded / leaks - H / C sink supply valve corroded / leaks - H / C sink supply valve corroded / leaks - H / C no 240 volt outlet was located no power to 240 volt outlet 240 volt outlet damaged / improper / missing cover gas supply was shut down flex gas line routed thru wall improper gas connection dryer does not vent to exterior no provision for venting of dryer s c N/A stains / discoloration / patching / damaged hardware missing / damaged hardware missing / damaged screens - damaged / missing ungrounded outlets (2/3 prong) / rever	sink / washer faucet handle corroded / missing improper drain / vent / trap sink not securely fastened / damaged no shut-off valves at washer supply hook-ups not visible (not inspected) 240 volt outlet loose back draft damper missing / damaged duct separated / disconnected flex dryer duct exceeds 6' odor of gas - needs immediate evaluation of cracks - hairline / 1/16" / 1/8" / 1/8"+ / numerous ge / cracks - hairline / 1/16" / 1/8" / 1/8"+ / numerous

	= Recommend a specialty contractor further inspect to determine and special sp	^
<u>(4</u>	= Informational	ars to function as it was designed to do
	PLUMBING	
Water Supply	Copper * Galvanized Polybutylene - PB (copper fi	
	water piping system which has developed a reputation for premature failure (i.e., of piping for further information and evaluation of risk factors. * Doc	breakage, cracks, etc.). You should contact the piping as not rule out possibility of PB or Galv. pipe inside walls
53 Main Shut Off	locationpsi	
Regulator installed? Y/N not located	☐ main shut off not located / broken / leaks ☐ pressure too high - normal is 40-80 psi	dissimilar metal pipe used possible slab leak
○ Satisfactory	regulator leaking / damaged / corrosion / in soil	☐ leaks at hose spigots
Water was shut off at time of inspection	☐ leakage / damaged / corroded	pressure relief valve deficient / absent
- limited inspection.	improper material / connections	2
		^
54 Fuel Supply	Natural Gas Propane (tank not evaluated	,
✓ Satisfactory✓ Gas was shut off at	 exterior piping is not protected from corrosion gas smell (call gas company immediately) 	☐ improper installation☐ improper material / connections
time of inspection	propane tank not protected against impact	
<u> </u>		
55 Water Heater	Type: Gas Electric C	Solar (these systems are not tested / evaluated)
Size: Gallons:	Location: Garage Interior Exterior Patio	
Age: (approx)	pilot not lit - status not evaluated	t & p drain is greater than 6" from floor or not vented to the exterior
Seismic Straps?	☐ leakage / damage / rust & corrosion ☐ seismic straps missing	no t & p valve installed
Y/N Satisfactory	inadequate size straps and / or method of strapping	flame quality poor at burner insul. blanket obscures wtr.htr Limited inspection
	seismic strap bolts less than 1/4" diameter	stains at
	□ W/H not installed on 18" platform□ gas smell (call gas company immediately)	no protection against vehicle impact
	corrosion at water supply or valve	□ W/H support platform inadequate□ leak at shutoff / shutoff not installed
	temp. & pressure valve leaks / corroded	no drip pan (where water damage poss.)
	t & p drain line not installed / not 3/4 inch	drip pan - line not routed to exteriors
	t & p drain is improper material / has improper slope / termination not located	☐ drip pan - no overflow line☐ W/H at or near end of useful life
✓		W/A at or flear end or dserurine
56 Water Heater	venting improper / blocked / disconnected	improper materials for vent pipe
vent / venting	improper clearance to combustibles	uent connector / draft diverter missing
Satisfactory	vent duct not securely fastened / gaps at joint(s)	☐ combustion air improper / blocked
	vent duct has improper slope	☑
	ELECTRICAL	
Gamileo		
57 Service	☐ 120/240V ☐ 120V ☐ Overhead ☐ Undergrou ☐ overhead wires are frayed / improper type	service mast loose / damaged
○ Satisfactory	overhead wires do not have proper clearance from	☐ mast meter head loose / damaged
☐ Electricity to property was not on at time of inspection	ground / roof / driveway / walkway / yard	☐ no drip loop provided at mast
- limited inspection	☐ loose / damaged connections☐ wires touching trees	
58 Main Panel	Main breaker amps	akers 🗋 fuses - (older, limited service)
Location:	☐ recommend load calculation ☐ older, limited service	e: may not be adequate for modern usage
◯ Satisfactory	no main breaker (typically required with more than 6 circuits) # circuits	☐ improper grounding☐ circuits not labeled
	☐ main panel locked - not evaluated	blank breaker covers are missing
	circuit breakers damaged	☐ tie bars missing at 240 volt breakers☐ missing knock out seals
	☐ frayed / scorched wires☐ incorrect breaker size for wire	needs anti-oxidation material for
	double wiring on circuit breakers	aluminum wiring main panel penetrates firewall
	 cover is missing / loose / damaged hinges / screws missing wires enter into panel without proper protection 	neutral buss not bonded to panel
	☐ Federal style breakers - known to have a history of failure	ground / neutral buss bar missing / improper connection
	Bulldog panel w/ Pushmatic breakers	heat / scorch marks within panel
	☐ Zinsco panel - history of problems☐ no main breaker / disconnect	□ wires need capping□ panel wiring overfilled
	panel is not weather-tight	☐ circuit breaker is tripped☐ tripped breaker could not be reset
[7]	improper taps / connections	- tripped breaker could flot be reset

RECOMMENDATIONS (Rec.):	✓ = Recommend a specialty contractor further inspect to determine.	all repair options and costs.
	#1 = Recommend qualified termite inspector #2 = Recommend	^
	Satisfactory = item exists and appe	ears to function as it was designed to do
	ELECTRICAL (Continued)	
50 Minima 040M	^	
59 Wiring 240V	Copper Aluminum	
60 Wiring 120V	Copper* Aluminum * Does not rule out the p	presence of aluminum wiring in inaccessible areas.
Note: If aluminum wiring is noted in item	#49 above, it is recommended that this wiring be evaluated by a qualified electrician.	A full inspection of the system is recommended.
61 Sub-panel	circuit breakers fuses - (older, limited service)	
Location:	☐ recommend load calculation ☐ older, limited service	e: may not be adequate for modern usage
Oction	no breaker (typically required with more	improper grounding
Satisfactory	than 6 circuits) # circuits	circuits not labeled
♦ N/A	☐ sub-panel locked - not evaluated	blank breaker covers are missing
•	☐ circuit breakers damaged	tie bars missing at 240 volt breakers
	frayed / scorched wires	missing knock out seals
	incorrect breaker size for wire	needs anti-oxidation material for aluminum wiring
	double wiring on circuit breakers	☐ sub-panel penetrates firewall
	cover is missing / loose / damaged hinges / screws missing	neutral buss not bonded to sub-panel
	 wires enter into panel without proper protection Federal style breakers - known to have a history of failure 	ground / neutral buss bar missing / improper connection
	Bulldog panel w/ Pushmatic breakers	heat / scorch marks within sub-panel
	☐ Zinsco panel - history of problems	wires need capping
	no sub-panel breaker / disconnect	panel wiring overfilled
	□ sub-panel is not weather-tight	circuit breaker is tripped
	improper taps / connections	tripped breaker could not be reset
	HEATING	
62 Heater	Gas Electric Hydronic	
Type:	FAU Heat Pump Wall Floor	Wall - Direct Vent Baseboard
Location:	Hall / Liv. Rm. / Garage / Attic / Exterior / Underfloor / Roof / Patio	o / floor / ceiling
Satisfactory	pilot not lit / not on / no gas (check = status not evaluated)	☐ flame quality poor / flame rollout
	power disconnected - unit not evaluated	soot / charring in burner chamber
Temp. at return	damage / to unit / rusting	ilter was dirty / missing / improper size
Temp. at register	did not ignite or function using normal controls	improper installation
☐ Inadequate temperature	gas smell (call gas company immediately)	☐ base of unit not sealed / holes in platform
differential	improper use of flexible gas line - thru unit / wall	☐ radiant heat not functional
	☐ thermostat missing / damaged / loose / missing parts	stains noted at
	☐ this unit subject to a safety recall	☐ lacks a gas shut off valve
		unit is at / near end of useful life
63 Vents / Venting	venting improper	improper materials for vent pipe
Satisfactory	venting blocked / disconnected	vent connector / draft diverter missing
	vent pipe has negative pitch	combustion air improper / blocked
	improper clearance to combustibles	return air drawn from crawl space
	damaged vent ducting	vent connection improper
64 Ducts	☐ disconnected / crushed ducts	demand / missing registers
		☐ damaged / missing registers☐ low air volume
Satisfactory	insulation missing from ducts / deteriorated / loose	
	no air to	FAU not tested - unable to test ducting
/		
	AIR CONDITIONER	
65 A/C	^ ^	^
	Central A/C Heat Pump Evaporative Cooler	Wall Unit
Locations:	Roof Exterior Patio	1_
○ Satisfactory	damage / deterioration / rusting noted	condensate line - blocked / not installed
Temp. at return	A/C did not start / function properly	unable to locate drain termination
Temp. at register	leakage at refrigerant lines / connections	power supply disconnected
	refrigerant lines are not insulated	no local electrical disconnect provided
Outside air temperature is too low to test.	condensate drain line cracked / disconnected	improper conduit (interior type)
☐ Inadequate temperature	condensate drain line is missing trap / vent	condensing unit not on proper platform
differential	condensate line vent on uphill side of trap	evaporator coil seams need sealing
	condensate line has improper slope	evaporator coil leaking
	condensate line - no secondary installed	damaged fins on condensing unit
	☐ condensate line - discharges too close to structure	A/C unit at or near end of useful life
<u> </u>		
<u> </u>		

RECOMMENDATIONS (Rec.): = Recommend a specialty contractor further inspect to determine all repair options and costs.							
	#1 = Recommend qualified termite inspector #2 = Recommend qualified engineer N/A = Not applicable Informational Satisfactory = item exists and appears to function as it was designed to do						
		(= Inforn	nationa	Satisfactory = item exists and appe	ars to function as it was designed to do	
					FIREPLACE(S)		
66	Туре:		∩ Ма	asonry	☐ Factory ☐ Freestanding ☐ Deco	rative appliance	
	Location:		#1 = Li	iving ro	om #2 = Family room #3 = Bedroom	#4 =	
67	Firebox		∩ Ма	asonry	☐ Metal ☐ Panels		
	Satisfactory				- damaged panels	separation at interior corners	
Ŷ	•				lamaged / loose firebricks	gap at hole for gas pipe needs sealing	
\Diamond	N/A			•	/ deteriorated mortar is not UL listed; as such, we are unable to	efflorescence (possible water intrusion)	
					ne proper clearances to adjacent walls	missing / loose valve trim piece	
			_		r clearance to combustibles	acarbon deposits on gas logs	
				arped i			
Note	Note: Have chimney sweep further evaluate if: (i) cracks noted (possible costly repairs) and/or (ii) if dirty flue-firebox noted (adequate visual inspection not possible)						
68	Gas starter		Yes / N	No	Gas pipe was capped		
\circ	Satisfactory		☐ ga	as pipe	e is damaged	gas log starter – rusted	
	•		☐ fle	exible (gas tube should not be used with wood	control valve is in fireplace	
_ _							
69	Flue / liner		fire	e clay	precast concrete meta	parge coat (older type)	
	Satisfactory			•	oot covered	no flue liner	
	oution dottory				leaning	spalling parge coating	
		ļ	u cr	аскеа	flue liner	separation of flue liner	
70	Damper				is not functional	damper handle is damaged	
0	Satisfactory				is damaged / rusted	no damper installeddamper does not have clamp to prevent	
			u da	amper	handle is missing	full closure for gas log fireplaces	
71	Hearth / Mantle		☐ he	earth is	s less than standard size	wood mantle / facing does not have proper	
	Satisfactory		☐ he	earth is	s cracked / damaged	clearance from opening	
)	outistactory		☐ se	eparati	on between hearth and firebox	☐ mantle damaged / not secured☐ fireplace screen damaged / missing☐	
			☐ no	o hear	th provided	☐ fireplace glass door(s) damaged / missing	
			☐ sc	oot sta	ins on facing	fireplace door components missing / loose	
2 _							
					INTERIOR ROOMS		
COI	CODES: S = SATISFACTORY / SERVICEABLE (item exists and functions as it was designed to do)						
C = COMMENTS - item warrants evaluation, repair or replacement by a qualified specialist / contractor							
Nets	N/A = NOT APPLI		•	_			
NOTE	situated or stored are not inspect		orage bo)X63, 610	.) are not moved during the inspection. Therefore, areas of the	a menor where runnishings or personal property items are	
Rec.	#1 #2	S	С	N/A	ENTRY		
72	Floor						
73 74	Walls Ceiling				stains / discoloration / patching / damage / cra stains / discoloration / patching / damage / cra		
75	Doors				☐ stains / discoloration / patching / damage / cra ☐ hardware missing / damaged	ons - namine / 1/10 / 1/0 / 1/0 +/ numetous	
76	Windows				screens - damaged / missing		
77 78	Electrical Doorbell				ungrounded outlets (2/3 prong) / reversed poinoperable / damaged / loose	larity	
	Doorbell						
					Q	complete and limited by excess storage in room	
						complete and inflited by excess storage in room	
Rec.	#1 #2	S	c 	N/A	LIVING ROOM		
79 80	Floor Walls				stains / discoloration / patching / damage / cra	cks - hairline / 1/16" / 1/8" / 1/8"+ / numerous	
81	Ceiling		ā		stains / discoloration / patching / damage / cra		
82	Doors				hardware missing / damaged		
83	Windows Electrical				screens - damaged / missingungrounded outlets (2/3 prong) / reversed po	olarity	
	I					complete and limited by excess storage in room	
_	ne inspector could not fully avaluate	the so	ale on th	ם לווטן מ			
	The inspector could not fully evaluate the seals on the dual glazed (double pane) windows or doors due to conditions making it very difficult to detect defects, if any. These conditions may include lighting conditions, dirty surfaces, window height, partially blocked access, inclement weather, etc. Please consult a window contractor to rule out any problems with the seals.						

Fireplace(s) / Interior Rooms - Page 11

COI	S = SATISFACTORY / SERVICEABLE (item exists and functions as it was designed to do) C = COMMENTS - item warrants evaluation, repair or replacement by a qualified specialist / contractor N/A = NOT APPLICABLE (item does not apply)				
REC	COMMENDATIONS (Rec.):				d a specialty contractor further inspect to determine all repair options and costs. d qualified termite inspector #2 = Recommend qualified engineer
Note	Personal property (furniture, clo situated or stored are not inspec		torage b	oxes, etc	e.) are not moved during the inspection. Therefore, areas of the interior where furnishings or personal property items are
Rec.	#1 #2	S	С	N/A	FAMILY ROOM
<u>85</u> 86	Floor Walls				stains / discoloration / patching / damage / cracks - hairline / 1/16" / 1/8" / 1/8"+ / numerous
87	Ceiling		<u> </u>		stains / discoloration / patching / damage / cracks - hairline / 1/16" / 1/8" + / numerous
88	Doors				☐ hardware missing / damaged
89	Windows				□ screens - damaged / missing
90	Electrical				ungrounded outlets (2/3 prong) / reversed polarity
/ _					evaluations are incomplete and limited by excess storage in room
Rec.	#1 #2 Floor	s	С	N/A	DEN
91 92	Walls		 		stains / discoloration / patching / damage / cracks - hairline / 1/16" / 1/8" / 1/8"+ / numerous
93	Ceiling		<u> </u>		stains / discoloration / patching / damage / cracks - hairline / 1/16" / 1/8" + / numerous
94	Doors				☐ hardware missing / damaged
95	Windows				□ screens - damaged / missing
96	Electrical				ungrounded outlets (2/3 prong) / reversed polarity
☑ evaluations are incomplete and limited by excess storage in room					
Rec.	#1 #2	S	С	N/A	DINING ROOM
97	Floor				Distains / dissolaration / notabion / domons / aradia, haiding / 4/40" / 4/0" / 4/0", / numerous
98	Walls Ceiling			-	stains / discoloration / patching / damage / cracks - hairline / 1/16" / 1/8" / 1/8"+ / numerous stains / discoloration / patching / damage / cracks - hairline / 1/16" / 1/8" / 1/8"+ / numerous
100	Doors				hardware missing / damaged
101	Windows		H		screens - damaged / missing
102	Electrical		ā		ungrounded outlets (2/3 prong) / reversed polarity
					evaluations are incomplete and limited by excess storage in room
D	"4 "0			N1/A	DINETTE
Rec.	#1 #2	S	С	N/A	DINETTE
103	Floor				District / dissolvation / notabing / domogo / grooks hairling / 4/40" / 4/0" / 4/0" / numorous
104 105	Walls Ceiling		H		stains / discoloration / patching / damage / cracks - hairline / 1/16" / 1/8" + 1/8"+ / numerous stains / discoloration / patching / damage / cracks - hairline / 1/16" / 1/8" + 1/8"+ / numerous
106	Doors		H		hardware missing / damaged
107	Windows		ā		screens - damaged / missing
108	Electrical				ungrounded outlets (2/3 prong) / reversed polarity
			_		evaluations are incomplete and limited by excess storage in room
Rec.	#1 #2	s	С	N/A	KITCHEN
		ional sta		pliances	- he does not evaluate or test the adequacy or efficiency of appliances.
109	Floor				
110	Walls				stains / discoloration / patching / damage / cracks - hairline / 1/16" / 1/8" / 1/8"+ / numerous
111	Ceiling				stains / discoloration / patching / damage / cracks - hairline / 1/16" / 1/8" / 1/8"+ / numerous
112	Doors				hardware missing / damaged
113	Windows				□ screens - damaged / missing □ ungrounded outlets (2/3 prong) / reversed polarity / recommend GFCI at counter outlets
114 115	Electrical GFCI Yes / No Cabinets / Countertops				☐ stains / discoloration / patching / cracking / damage ☐ Stored items precludes full inspection
116	Sink / Faucet				☐ Chips in sink ☐ Faucet Leaks
117	Caulking needed		<u> </u>		sink faucet backsplash counter
118	2				corrosion at water supply / drains
119	Water valves / Drains		ā		a corresion at water supply / drains
113	Water valves / Drains Disposal				usting
120					
120 121	Disposal Dishwasher / air gap Stove – Oven Gas / Elec.				_ rusting _
120 121 122	Disposal Dishwasher / air gap Stove – Oven Gas / Elec. Cooktop Gas / Elec.				_ rusting _
120 121 122 123	Disposal Dishwasher / air gap Stove – Oven Gas / Elec. Cooktop Gas / Elec. Oven Gas / Elec.				rusting obstruction in drain line air gap not installed
120 121 122 123 124	Disposal Dishwasher / air gap Stove – Oven Gas / Elec. Cooktop Gas / Elec. Oven Gas / Elec. Hood / Fan / Vent				_ rusting _
120 121 122 123 124 125	Disposal Dishwasher / air gap Stove – Oven Gas / Elec. Cooktop Gas / Elec. Oven Gas / Elec. Hood / Fan / Vent Microwave				rusting obstruction in drain line air gap not installed
120 121 122 123 124 125 126	Disposal Dishwasher / air gap Stove – Oven Gas / Elec. Cooktop Gas / Elec. Oven Gas / Elec. Hood / Fan / Vent				rusting obstruction in drain line air gap not installed
120 121 122 123 124 125	Disposal Dishwasher / air gap Stove – Oven Gas / Elec. Cooktop Gas / Elec. Oven Gas / Elec. Hood / Fan / Vent Microwave				rusting obstruction in drain line air gap not installed
120 121 122 123 124 125 126	Disposal Dishwasher / air gap Stove – Oven Gas / Elec. Cooktop Gas / Elec. Oven Gas / Elec. Hood / Fan / Vent Microwave				rusting obstruction in drain line air gap not installed dirty / missing filter vent improper
120 121 122 123 124 125 126	Disposal Dishwasher / air gap Stove – Oven Gas / Elec. Cooktop Gas / Elec. Oven Gas / Elec. Hood / Fan / Vent Microwave				rusting obstruction in drain line air gap not installed dirty / missing filter vent improper Exposed (unprotected) Romex at
120 121 122 123 124 125 126	Disposal Dishwasher / air gap Stove – Oven Gas / Elec. Cooktop Gas / Elec. Oven Gas / Elec. Hood / Fan / Vent Microwave Trash Compactor		als on the		rusting obstruction in drain line air gap not installed dirty / missing filter vent improper Exposed (unprotected) Romex at

COI	DES: S = SATISFAC	TORY	/ SER	/ICEAE	BLE (item exists and functions as it was designed to do)							
C = COMMENTS - item warrants evaluation, repair or replacement by a qualified specialist / contractor												
N/A = NOT APPLICABLE (item does not apply)												
REC	COMMENDATIONS (Rec.):		✓ = Recommend a specialty contractor further inspect to determine all repair options and costs.									
			#1 = Recommend qualified termite inspector #2 = Recommend qualified engineer									
Note	 Personal property (furniture, clo situated or stored are not inspect 		orage b	oxes, etc	.) are not moved during the inspection. Therefore, areas of the interior where furnishings or personal property items are							
Rec.	#1 #2	S	С	N/A	HALL 1st floor 2nd floor							
127	Floor											
128	Walls / Handrails				stains / discoloration / patching / damage / cracks - hairline / 1/16" / 1/8" / 1/8"+ / numerous							
129 130	Ceiling Doors				stains / discoloration / patching / damage / cracks - hairline / 1/16" / 1/8" / 1/8"+ / numerous hardware missing / damaged							
131	Windows		<u> </u>		screens - damaged / missing							
132	Electrical				ungrounded outlets (2/3 prong) / reversed polarity							
133	Cabinets / Closets				stored items obstructed visual access to some areas							
134	Smoke Detector				does not function recommend installing one							
<u>_</u>					evaluations are incomplete and limited by excess storage in room							
Rec.	#1 #2	s	С	N/A	HALL-STAIRS 1st floor 2nd floor							
135	Floor / Steps											
136	Walls / Handrails				stains / discoloration / patching / damage / cracks - hairline / 1/16" / 1/8" / 1/8"+ / numerous							
137	Ceiling				stains / discoloration / patching / damage / cracks - hairline / 1/16" / 1/8" / 1/8"+ / numerous							
138 139	Doors Windows				□ hardware missing / damaged □ screens - damaged / missing							
140	Electrical				ungrounded outlets (2/3 prong) / reversed polarity							
141	Cabinets / Closets				stored items obstructed visual access to some areas							
142	Smoke Detector				☐ does not function ☐ recommend installing one							
_ _												
_ _					evaluations are incomplete and limited by excess storage in room							
Rec.	#1 #2	s	С	N/A	BEDROOM #1 1st floor 2nd floor master left right front middle rear							
143	Floor											
144	Walls				stains / discoloration / patching / damage / cracks - hairline / 1/16" / 1/8" / 1/8"+ / numerous							
145	Ceiling				stains / discoloration / patching / damage / cracks - hairline / 1/16" / 1/8" / 1/8"+ / numerous							
146 147	Doors Windows				hardware missing / damaged screens - damaged / missing							
148	Electrical				ungrounded outlets (2/3 prong) / reversed polarity							
149	Cabinets / Closets		ō		stored items obstructed visual access to some areas							
150	Smoke Detector				☐ does not function ☐ recommend installing one							
<u> </u>												
_ _					evaluations are incomplete and limited by excess storage in room							
Rec.	#1 #2	s	С	N/A	BEDROOM #2 1st floor 2nd floor master left right front middle rear							
151	Floor											
152	Walls				stains / discoloration / patching / damage / cracks - hairline / 1/16" / 1/8" / 1/8"+ / numerous							
153	Ceiling				stains / discoloration / patching / damage / cracks - hairline / 1/16" / 1/8" / 1/8"+ / numerous							
154 155	Doors Windows				hardware missing / damaged screens - damaged / missing							
156	Electrical		7		ungrounded outlets (2/3 prong) / reversed polarity							
157	Cabinets / Closets				stored items obstructed visual access to some areas							
158	Smoke Detector				☐ does not function ☐ recommend installing one							
<u>_</u>												
<u>_</u> _												
<u> </u>					evaluations are incomplete and limited by excess storage in room							
Rec.	#1 #2	S	С	N/A	BEDROOM #3 1st floor 2nd floor master left right front middle rear							
159	Floor											
160	Walls				stains / discoloration / patching / damage / cracks - hairline / 1/16" / 1/8" / 1/8" + / numerous							
161 162	Ceiling Doors				stains / discoloration / patching / damage / cracks - hairline / 1/16" / 1/8" / 1/8"+ / numerous hardware missing / damaged							
163	Windows				screens - damaged / missing							
164	Electrical				ungrounded outlets (2/3 prong) / reversed polarity							
165 166	Cabinets / Closets				□ stored items obstructed visual access to some areas □ does not function □ recommend installing one							
	Smoke Detector		J		☐ does not function ☐ recommend installing one							
☑ _ ☑ _					Davidiona are in a constate and the first of the constant of							
	an inconcetor accellent of the concetor	n 41- :	ole :	ا المامية	evaluations are incomplete and limited by excess storage in room							
					lazed (double pane) windows or doors due to conditions making it very difficult to detect defects, if any. These conditions may tially blocked access, inclement weather, etc. Please consult a window contractor to rule out any problems with the seals.							

COI	CODES: S = SATISFACTORY / SERVICEABLE (item exists and functions as it was designed to do) C = COMMENTS - item warrants evaluation, repair or replacement by a qualified specialist / contractor N/A = NOT APPLICABLE (item does not apply)											
REC	COMMENDAT		 ✓ = Recommend a specialty contractor further inspect to determine all repair options and costs. #1 = Recommend qualified termite inspector #2 = Recommend qualified engineer 									
Note	Note: Personal property (furniture, clothing, storage boxes, etc.) are not moved during the inspection. Therefore, areas of the interior where furnishings or personal property items are situated or stored are not inspected.											
Rec.	#1 #	2	S	С	N/A	BEDROOM #4 1st floor 2nd floor master left right front middle rear						
167	Floor											
168 169	Walls Ceiling					stains / discoloration / patching / damage / cracks - hairline / 1/16" / 1/8" / 1/8"+ / numerous stains / discoloration / patching / damage / cracks - hairline / 1/16" / 1/8" / 1/8"+ / numerous						
170	Doors			<u> </u>		hardware missing / damaged						
171	Windows			<u> </u>		screens - damaged / missing						
172	Electrical					ungrounded outlets (2/3 prong) / reversed polarity						
173	Cabinets /					stored items obstructed visual access to some areas						
174	Smoke De	tector				does not function recommend installing one						
_ _												
<u> </u>												
<u> </u>						evaluations are incomplete and limited by excess storage in room						
Rec.	#1 #	2	S	С	N/A	BEDROOM #5 1st floor 2nd floor master left right front middle rear						
175 176	Floor Walls					stains / discoloration / patching / damage / cracks - hairline / 1/16" / 1/8" / 1/8"+ / numerous						
177	Ceiling			<u> </u>		stains / discoloration / patching / damage / cracks - hairline / 1/16" / 1/8" / 1/8" + / numerous						
178	Doors			ā		☐ hardware missing / damaged						
179	Windows					screens - damaged / missing						
180	Electrical	Olasata				ungrounded outlets (2/3 prong) / reversed polarity						
181 182	Cabinets / Smoke De					□ stored items obstructed visual access to some areas □ does not function □ recommend installing one						
	Ciriono Do											
/ _												
2 _												
<u>_</u>		_				evaluations are incomplete and limited by excess storage in room						
Rec.	#1 #	2	S	С	N/A	BEDROOM #6 1st floor 2nd floor master left right front middle rear						
183	Floor											
184	Walls					stains / discoloration / patching / damage / cracks - hairline / 1/16" / 1/8" / 1/8"+ / numerous						
185	Ceiling					stains / discoloration / patching / damage / cracks - hairline / 1/16" / 1/8" / 1/8"+ / numerous						
186 187	Doors Windows					□ hardware missing / damaged □ screens - damaged / missing						
188	Electrical			H		ungrounded outlets (2/3 prong) / reversed polarity						
189	Cabinets /	Closets				stored items obstructed visual access to some areas						
190	Smoke De	tector				does not function recommend installing one						
_												
_												
_						evaluations are incomplete and limited by excess storage in room						
	44 44			_	NI/A	BATHROOM #1 1st floor 2nd floor master hall 1/2 bath middle B/R						
Rec.	#1 #:	2	S	С	N/A	1st floor 2nd floor master hall 1/2 bath middle B/R						
191 192	Floor Walls					stains / discoloration / patching / damage / cracks - hairline / 1/16" / 1/8" / 1/8"+ / numerous						
192	Ceiling					stains / discoloration / patching / damage / cracks - hairline / 1/16" / 1/8" / 1/8" + / numerous						
194	Door					hardware missing / damaged						
195	Window					□ screens - damaged / missing						
196	Exhaust Fa					□ noisy □ does not function □ ungrounded outlets (2/3 prong) / reversed polarity / recommend GFCI at counter outlets						
197 198	Heating	GFCI Yes / No				ungrounded outlets (2/3 prong) / reversed polarity / recommend GPCr at counter outlets						
199	Sink / Faud	et		<u> </u>		☐ sink chips / rusting / cracks ☐ H-C leaks ☐ H-C damage (corrosion, etc.) ☐ hot/cold reversed						
200	Sink drain /	water supply				corrosion at water supply / drains						
201	Cabinets /	Countertop				stains / discoloration / patching / cracking / damage						
202	Toilet	ver / Combo				□ loose at base □ corrosion at water supply □ chips / cracks						
203 204	Tub / Snov	rei / CUITIDO				☐ H-C leaks ☐ H-C damage (corrosion, etc.) ☐ hot/cold reversed						
205		ombo valves				☐ H-C leaks ☐ H-C damage (corrosion, etc.) ☐ hot/cold reversed						
206	Tub / Show	er drain				☐ slow to drain ☐ clogged ☐ diverter is defective						
207	Glass encl					Safety glass Yes / No 🖵 corrosion						
208	Caulking n	eeded				floor / sink / counter / sink faucet / tub / shower / shower arm / tub valves / shower valves / tub spout / toilet base						
_ _												
_ _												
Note:	Note: (i) Stains may or may not indicate a current leakage problem. This can only be determined with a water test of the roof, which is beyond the scope of the inspection.											
Note: items under sink / in cabinets of bathroom(s) obstruct view - this is a limited inspection The inspector was unable to rule out problems with the dual glazed (double page) windows or doors because several conditions may exist making detection of defects very difficult												

■ The inspector was unable to rule out problems with the dual glazed (double pane) windows or doors because several conditions may exist making detection of defects very difficult (e.g. lighting conditions, dirty surfaces, window height, partially blocked access, inclement weather). Please consult a window contractor to rule out any problems with the seals.

CODES: S = SATISFACTORY / SERVICEABLE (item exists and functions as it was designed to do) C = COMMENTS - item warrants evaluation, repair or replacement by a qualified specialist / contractor N/A = NOT APPLICABLE (item does not apply)								
RECOMMENDATIONS (Rec.): = Recommend a specialty contractor further inspect to determine all repair options and costs. #1 = Recommend qualified termite inspector #2 = Recommend qualified engineer								
Rec.	#1 #2	s	С	N/A	BATHROOM #2 1st floor 2nd floor master hall 1/2 bath middle B/F			
209	Floor				stains / discoloration / patching / damage / cracks - hairline / 1/16" / 1/8" / 1/8"+ / numerous			
210 211	Walls Ceiling				stains / discoloration / patching / damage / cracks - hairline / 1/16" / 1/8" / 1/8" + / numerous			
212	Door				hardware missing / damaged			
213 214	Window Exhaust Fan				screens - damaged / missing noisy does not function			
215	Electrical GFCI Yes / No		ā		ungrounded outlets (2/3 prong) / reversed polarity / recommend GFCI at counter outlets			
216	Heating				District to the District Distr			
217 218	Sink / Faucet Sink drain / water supply				sink chips / rusting / cracks H-C leaks H-C damage (corrosion, etc.) hot/cold reversed corrosion at water supply / drains			
219	Cabinets / Countertop		ā		stains / discoloration / patching / cracking / damage			
220	Toilet				□ loose at base □ corrosion at water supply			
221	Tub / Shower / Combo Tub valves				☐ chips / cracks ☐ H-C leaks ☐ H-C damage (corrosion, etc.) ☐ hot/cold reversed			
223	Shower / Combo valves		<u></u>		☐ H-C leaks ☐ H-C damage (corrosion, etc.) ☐ hot/cold reversed			
224	Tub / Shower drain				□ slow to drain □ clogged □ diverter is defective			
225 226	Glass enclosure Caulking needed				Safety glass Yes / No corrosion floor / sink / counter / sink faucet / tub / shower / shower arm / tub valves / shower valves / tub spout / toilet base			
	Caagccaca				Tion / sink / counter / sink radect / tab / shower / shower ann / tab valves / shower valves / tab spout / tollet base			
Rec.	#1 #2	s	С	N/A	BATHROOM #3 1st floor 2nd floor master hall 1/2 bath middle B/F			
227	Floor							
228	Walls				stains / discoloration / patching / damage / cracks - hairline / 1/16" / 1/8" + / numerous			
229 230	Ceiling Door				stains / discoloration / patching / damage / cracks - hairline / 1/16" / 1/8" / 1/8"+ / numerous hardware missing / damaged			
231	Window		<u> </u>		screens - damaged / missing			
232	Exhaust Fan				noisy does not function			
233 234	Electrical GFCI Yes / No				ungrounded outlets (2/3 prong) / reversed polarity / recommend GFCI at counter outlets			
235	Heating Sink / Faucet		 		☐ sink chips / rusting / cracks ☐ H-C leaks ☐ H-C damage (corrosion, etc.) ☐ hot/cold reversed			
236	Sink drain / water supply		ā		corrosion at water supply / drains			
237	Cabinets / Countertop				stains / discoloration / patching / cracking / damage			
238 239	Toilet Tub / Shower / Combo				□ loose at base □ corrosion at water supply □ chips / cracks			
240	Tub valves		ō		☐ H-C leaks ☐ H-C damage (corrosion, etc.) ☐ hot/cold reversed			
241	Shower / Combo valves				☐ H-C leaks ☐ H-C damage (corrosion, etc.) ☐ hot/cold reversed			
242 243	Tub / Shower drain Glass enclosure				□ slow to drain □ clogged □ diverter is defective Safety glass Yes / No □ corrosion			
244	Caulking needed				floor / sink / counter / sink faucet / tub / shower / shower arm / tub valves / shower valves / tub spout / toilet base			
Rec.	#1 #2	s	С	N/A	BATHROOM #4 1st floor 2nd floor master hall 1/2 bath middle B/f			
245	Floor				IST 11001 ZIIQ 11001 IIIaStel IIali I/Z batii IIIIquie Bri			
246	Walls		<u> </u>		stains / discoloration / patching / damage / cracks - hairline / 1/16" / 1/8" / 1/8"+ / numerous			
247	Ceiling				stains / discoloration / patching / damage / cracks - hairline / 1/16" / 1/8" / 1/8"+ / numerous			
248 249	Door Window				□ hardware missing / damaged □ screens - damaged / missing			
250	Exhaust Fan		1		noisy does not function			
251	Electrical GFCI Yes / No				ungrounded outlets (2/3 prong) / reversed polarity / recommend GFCI at counter outlets			
252	Heating				Designation (marked product D. 11.01. 1. D.			
253 254	Sink / Faucet Sink drain / water supply				sink chips / rusting / cracks H-C leaks H-C damage (corrosion, etc.) hot/cold reversed corrosion at water supply / drains			
255	Cabinets / Countertop		ō		stains / discoloration / patching / cracking / damage			
256	Toilet				☐ loose at base ☐ corrosion at water supply			
257 258	Tub / Shower / Combo Tub valves				☐ chips / cracks ☐ H-C leaks ☐ H-C damage (corrosion, etc.) ☐ hot/cold reversed			
259	Shower / Combo valves		<u> </u>		☐ H-C leaks ☐ H-C damage (corrosion, etc.) ☐ hot/cold reversed			
260	Tub / Shower drain				□ slow to drain □ clogged □ diverter is defective			
261	Glass enclosure				Safety glass Yes / No corrosion			
262	Caulking needed	<u> </u>			floor / sink / counter / sink faucet / tub / shower / shower arm / tub valves / shower valves / tub spout / toilet base			
Note:	(1) O(-in-	- (-		-1				
Note:	(I) <u>Stains</u> may or may not indica	_			roblem. This can only be determined with a water test of the roof, which is beyond the scope of the inspection. as under sink / in cabinets of bathroom(s) obstruct view - this is a limited inspection			
					glazed (double pane) windows or doors because several conditions may exist making detection of defects very difficult ally blocked access, inclement weather). Please consult a window contractor to rule out any problems with the seals.			